

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2020

Submitted Date:

10/27/2020

Document Number:

699501836**FIELD INSPECTION FORM**Loc ID 453711 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453704	WELL	PR	11/01/2018	OW	123-46259	QUARTER CIRCLE 24-11HZ	PR
453705	WELL	PR	11/01/2018	OW	123-46260	QUARTER CIRCLE 24-8HZ	PR
453706	WELL	PR	12/18/2018	OW	123-46261	QUARTER CIRCLE 24-10HZ	PR
453707	WELL	PR	12/18/2018	OW	123-46262	QUARTER CIRCLE 24-9HZ	PR
453708	WELL	PR	12/16/2018	OW	123-46263	QUARTER CIRCLE 24-6HZ	PR
453709	WELL	PR	12/23/2018	OW	123-46264	QUARTER CIRCLE 24-1HZ	PR
453710	WELL	PR	11/01/2018	OW	123-46265	QUARTER CIRCLE 24-5HZ	PR
453712	WELL	PR	12/22/2018	OW	123-46266	QUARTER CIRCLE 24-2HZ	PR
453713	WELL	PR	12/22/2018	OW	123-46267	QUARTER CIRCLE 24-3HZ	PR
453714	WELL	PR	12/16/2018	OW	123-46268	QUARTER CIRCLE 24-7HZ	PR
453715	WELL	PR	12/22/2018	OW	123-46269	QUARTER CIRCLE 24-4HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift

6

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Electric / automation

Corrective Action:

Date:

Type: Bradenhead

6

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>453704</u>	Type: <u>WELL</u>	API Number: <u>123-46259</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453705</u>	Type: <u>WELL</u>	API Number: <u>123-46260</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453706</u>	Type: <u>WELL</u>	API Number: <u>123-46261</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453707</u>	Type: <u>WELL</u>	API Number: <u>123-46262</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453708</u>	Type: <u>WELL</u>	API Number: <u>123-46263</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453709</u>	Type: <u>WELL</u>	API Number: <u>123-46264</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing Well

Comment: <u>PR</u>	
Corrective Action: <u></u>	Date: <u></u>

Facility ID: <u>453710</u>	Type: <u>WELL</u>	API Number: <u>123-46265</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453712</u>	Type: <u>WELL</u>	API Number: <u>123-46266</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453713</u>	Type: <u>WELL</u>	API Number: <u>123-46267</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453714</u>	Type: <u>WELL</u>	API Number: <u>123-46268</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>453715</u>	Type: <u>WELL</u>	API Number: <u>123-46269</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Producing Well

Comment: <u>PR</u>	
Corrective Action: <u></u>	Date: <u></u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were cold, sunny, recent snow.	medinaj	10/27/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501837	Pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5278817