

FORM  
INSPRev  
X/15State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/19/2020

Submitted Date:

10/22/2020

Document Number:

688308812

## FIELD INSPECTION FORM

 Loc ID 304630 Inspector Name: Sherman, Susan On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: 10699  
 Name of Operator: OWN RESOURCES OPERATING LLC  
 Address: 38 PALMER CREST CT  
 City: SPRING State: TX Zip: 77381
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

1 Number of Corrective Actions

 Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269512	WELL	PR	01/26/2006	GW	125-08789	KOENING 2-3	PR

**General Comment:**

Routine Inspection

Flow line leak at wellhead (see attached photos).

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:	
Comment:	<input type="text" value="970-332-3585"/>
Corrective Action:	<input type="text"/> Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No  
 Comment:   
 Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Prime Mover	# 1		
Comment:	electric		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	At CR L, chart, shed, calibration sheet		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Flow line leak at wellhead. Produced water is off location and in irrigated.crop field.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Remove and properly dispose of stained soil.		Date: <u>10/23/2020</u>
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	#		
Comment:	Bradenhead will need to be installed per new 11/2/2020 rule.		
Corrective Action:			Date:

Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 269512      CDP: \_\_\_\_\_

Comment:

Corrective Action:       Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:       Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:       Date: \_\_\_\_\_

**Comment:**

**Corrective Action:**       Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:  
 Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:  
 Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_  
 Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:  
 Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Inspected Facilities**

Facility ID: 269512 Type: WELL API Number: 125-08789 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR. 8/1/2020 production reported to COGCC database.](#)

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402517242	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276123">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276123</a>
688308845	OWN Resources Koenig 2-3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276120">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276120</a>