

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Mechanical issue near pumping unit motor see pic 1		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	11/22/2020
Type	OTHER		
Comment:	stained soil by pumping unit motor see pic 1		
Corrective Action:	Comply with 603 f.	Date:	11/22/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type:			corrective date
Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Prime Mover	# 1		
Comment:	gas motor		
Corrective Action:		Date:	
Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241909 Type: WELL API Number: 123-09700 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 10/22/20 at approximately 1120 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Moser 1-A Company Name- KPK API- 05-12309700 In Weld County Colorado. While there, I observed Producing well During this inspection the following possible compliance issues were observed: Stained soil by pumping unit motor see pic 1 Comply with 603 f. 11/22/20 Mechanical issue near pumping unit motor see pic 1 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. 11/22/20 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were overcast and calm.</p> <p>This is a summary of inspection report.</p>	medinaj	10/22/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402517203	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276075
699501801	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5276061