

Inspection Photos
Operator: Kinder Morgan
API: 083-06573
Date: 10/27/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western portion of the interim reclamation area from the southwestern corner facing northward. Revegetation is progressing, largely with rubber rabbitbrush, Indian ricegrass, and young junipers.



Photo 3. View of erosional channeling within the northwestern project area, approximately 2-3 feet wide and 6-8 inches deep.



Photo 4. View of erosional stream along the northwestern boundary of the project area.



Photo 5. View of the reference area comprised of pinyon/juniper woodland with understory of shrubs, forbs, and grasses such as yucca, sagebrush, mountain mahogany, Indian ricegrass, purple threeawn, rock goldenrod, and ephedra.