

Inspection Photos
Operator: Kinder Morgan
API: 083-06527
Date: 10/27/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western portion of the interim reclamation area from the southwestern corner facing northward. Revegetation is progressing, largely with rubber rabbitbrush, fourwing saltbush, Indian ricegrass, and western wheatgrass.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of the reference area comprised of pinyon/juniper woodland with understory of shrubs, forbs, and grasses such as yucca, sagebrush, mountain mahogany, Indian ricegrass, purple threeawn, rock goldenrod, and ephedra.