

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

10/30/2020

Submitted Date:

10/31/2020

Document Number:

699601959**FIELD INSPECTION FORM**
 Loc ID 303774 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253581	WELL	PR	11/12/1993	GW	125-07459	MEKELBURG 6-30	PR

**General Comment:**[Routine FIR](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Cropland with seasonal access		
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	GMR		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: NA

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Calibration cert in place. Central MR (2)		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:	NA		
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:	NA		
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 253581	Type: WELL	API Number: 125-07459	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	GW			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Cropland with rotational tillage](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699601960	GMR - Signage - Sep.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5281852">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5281852</a>