

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2020

Submitted Date:

10/29/2020

Document Number:

679603440

FIELD INSPECTION FORM
 Loc ID 461838 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10177

Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	720-279-5512	smiller@enerplus.com	All RI/CI inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450731	WELL	XX	02/11/2019		123-44899	CACHE LA POUDRE 8-67-33-4C	ND
450733	WELL	XX	02/11/2019		123-44900	MANCOS 8-67-33-4C	ND
450734	WELL	XX	02/11/2019		123-44901	BIG THOMPSON 8-67-33-4C	ND
450735	WELL	XX	02/11/2019		123-44902	RIO GRANDE 8-67-33-4C	ND
450736	WELL	PR	05/01/2020	OW	123-44903	ARKANSAS 8-67-33-4N	PR
450737	WELL	XX	03/31/2019		123-44904	SAN JUAN 8-67-33-4C	ND
450738	WELL	XX	02/11/2019		123-44905	COLORADO 8-67-33-4N	ND
450739	WELL	XX	02/11/2019		123-44906	PLATTE 8-67-33-4C	ND
461837	WELL	PR	09/01/2019	OW	123-49663	Avignon 8-67-32-31	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	2 tanks do not contain labeling. See attached photo.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	12/29/2020
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		

Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	UNKNOWN	
Other (Capacity)	UNKNOWN	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLS	STEEL AST		40.623700,-104.904100
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 450731 Type: WELL API Number: 123-44899 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 401893968 expires FEBRUARY 2021

Corrective Action: Date:

Facility ID: 450733 Type: WELL API Number: 123-44900 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 401893945 expires FEBRUARY 2021

Corrective Action: Date:

Facility ID: 450734 Type: WELL API Number: 123-44901 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 401893911 expires FEBRUARY 2021

Corrective Action: Date:

Facility ID: 450735 Type: WELL API Number: 123-44902 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 401893103 expires FEBRUARY 2021

Corrective Action: Date:

Facility ID: 450736 Type: WELL API Number: 123-44903 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

Facility ID: 450737 Type: WELL API Number: 123-44904 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 401893930 expires FEBRUARY 2021

Corrective Action:

Date:

Facility ID: 450738

Type: WELL

API Number: 123-44905

Status: XX

Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 401893889 expires FEBRUARY 2021

Corrective Action:

Date:

Facility ID: 450739

Type: WELL

API Number: 123-44906

Status: XX

Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED

Form 2 DOC#: 401893996 expires FEBRUARY 2021

Corrective Action:

Date:

Facility ID: 461837

Type: WELL

API Number: 123-49663

Status: PR

Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary **Weather Conditions: sunny, snow On Thursday, October 29, 2020 at approximately 08:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at COLORADO RIVERS PAD (Enerplus Resources (USA) Corporation), at location #: 461838 in WELD COUNTY Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. Two tanks do not display capacity/NFPA placard/contents. Install sign to comply with Rule 210.d. (Corrective Action Date: December 29, 2020) See attached photo #4.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	10/29/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603441	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282080