

**TEP ROCKY MOUNTAIN LLC**  
**UIC Handling Location 33-6S-95W**  
**Location ID: 445074**



**Tank label on 500 bbl tank is blacked out.**



**TEP ROCKY MOUNTAIN LLC**  
**UIC Handling Location 33-6S-95W**  
**Location ID: 445074**



**2 out of service 500 bbl heated tanks with stacks off of the heat units.**



**Stacks have been removed from the tank heating units. There is no covers over the open flange for the exhaust stacks.**



**TEP ROCKY MOUNTAIN LLC**  
**UIC Handling Location 33-6S-95W**  
**Location ID: 445074**



**Earthen berm has washed and sediment build up inside of berm.**



**TEP ROCKY MOUNTAIN LLC**  
**UIC Handling Location 33-6S-95W**  
**Location ID: 445074**



**Flow line ran under access road is causing road ditch to build up sediment and eroding around the poly pipe.**



**TEP ROCKY MOUNTAIN LLC**  
**UIC Handling Location 33-6S-95W**  
**Location ID: 445074**



**Flow line ran under access road is causing road ditch to build up sediment and eroding around the poly pipe.**



**TEP ROCKY MOUNTAIN LLC**  
**UIC Handling Location 33-6S-95W**  
**Location ID: 445074**



**Sheet of sheet metal from tin shed on location is laying out in field south west of location on wet side of the access road.**