

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/26/2020

Submitted Date:

10/27/2020

Document Number:

696302592**FIELD INSPECTION FORM**Loc ID 317496 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 42950Name of Operator: INDUSTRIAL GAS SERVICES INCAddress: 4891 INDEPENDENCE ST STE 200City: WHEATRIDGE State: CO Zip: 80033**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments7 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Allison, Rick		rick.allison@state.co.us	
,		igsinc@att.net	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238354	WELL	SI	05/01/2016	GW	123-05198	BEHRING 1	SI

General Comment:

This is a Follow-Up WELL & BATTERY inspection to FIR 6963021782 dated 05.04.202 and FIR 696100832 dated 04.29.2019

Well: SI

Entire battery & equipment is shut-down.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Weed encroachment at wellsite & pit excavation area. Remove, manage, & control weeds around wellsite. Refer to Rule 603.f. See photos		
Corrective Action:	Comply with Rule 603.f.	Date:	05/10/2019
Type	UNUSED EQUIPMENT		
Comment:	Prior FIR: Unused Equipment (Pipe) at S. side of pit. Refer to Rule 603.f for guidance. (30 Days). Remove unused equipment at S. side of pit. Comply w/ Rule 603.f. Original Corrective Action date: 11/17/2016. See photos		
Corrective Action:	Remove unused equipment at S. side of pit. Comply w/ Rule 603.f. Original Corrective Action date: 11/17/2016. Prior CA remains applicable.	Date:	11/17/2016

Overall Good: ☐

Spills:			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Prior FIR: Stained soil at wellsite. Stained soil at pumping unit engine house. Stained soil at crude oil tanks loadout. Remove or remediate stained soil & oily waste. Material around wellhead and Gas Engine has been worked but impacted soil remains in place. Visual and odor evidence of hydrocarbon impacts to soil remain present. Original Corrective Action date: 09/19/2016. See photos Prior CA remains applicable.		
Corrective Action:	Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Oily soil must be handled in accordance with Rule 907.e. but cannot be added to existing land treatment area - see remediation section of this inspection report regarding land treatment area. Original Corrective Action date: 09/19/2016. See photos. Prior CA remains applicable.		Date: 09/19/2016

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead does NOT appear plumbed to surface. Refer to Warning Letter 402359758 for Bradenhead Test Corrective Actions and Dates		
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	Prior FIR: Flowlines from treater to former pit NOT properly abandoned. Refer to Rule 1103 for guidance. Original Corrective Action date: 03/20/2017. See photos		
Corrective Action:	Properly abandon flowlines to former pit. Comply w/ Rule 1103. Original Corrective Action date: 03/20/2017. See photos Prior CA remains applicable.		Date: 03/20/2017
Type: Prime Mover	# 1		
Comment:	Gas Engine. Stained soil at engine house. See Spills section.		
Corrective Action:			Date:
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PLASTIC AST		40.440350,-104.170070
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate	
Comment:	Prior FIR: Produced H2O tank berm integrity compromised. Erosion in and on berms. Maintain berms to comply w/ Rule 906.d(1). Original Corrective Action date: 04/09/2017.				
Corrective Action:	Maintain berms to comply w/ Rule 906.d(1). Original Corrective Action date: 04/09/2017. Prior CA remains applicable.			Date:	04/09/2017
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	OTHER	STEEL AST		40.440581,-104.169996
Comment:	Prior FIR: Rust on crude oil tank. Repair & paint tanks to comply w/ Rule 804 & 605.d (Visual & Mechanical conditions). Original Corrective Action date: 04/24/2018. See photos Prior CA remains applicable.				
Corrective Action:	Repair & paint tanks to comply w/ Rule 804 & 605.d (Visual & Mechanical conditions). Original Corrective Action date: 04/24/2018. See photos Prior CA remains applicable.			Date:	04/28/2018

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	210 BBLs and 500 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment:	Prior FIR: Crude oil tanks berm integrity compromised. Erosion & burrows in and on berms. Maintain berms to comply w/ Rule 906.d(1). Original Corrective Action date: 04/09/2017. See photos. Prior CA remains applicable.				
Corrective Action:	Maintain berms to comply w/ Rule 906.d(1). Original Corrective Action date: 04/09/2017. See photos. Prior CA remains applicable.			Date:	04/09/2017

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 238354 Type: WELL API Number: 123-05198 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI. Last produced Apr 2016. Current MIT as of 06/26/2019 per Approved Form 21 #1732418.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: 40.440308Long: -104.170424Reference Point: SEOther: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: **Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: NOOil Accumulation: NO2+ feet Freeboard: YESComment: **Prior FIR:**

Pit closure and soil remediation is in process. Soil does not yet comply with Table 910-1 Concentration Levels. Operator is directed to submit plan and timeframe for compliance with Table 910-1 Concentration Levels.

Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary: On Wednesday 10/07/2020 at approximately 11:14 hrs. I, Inspector, Erica Petrie, conducted an on-site Inspection at: Operator Name: INDUSTRIAL GAS SERVICES INC. Location Name: BEHRING 1 Location ID: 317496 Location County: Weld County, Colorado While there, I observed: Well - 1: Shut-In Entire battery & equipment is shut-down.</p> <p>Follow-up to FIR #696301782 dated 05/04/2020 FIR #684904636 dated 10/24/2017. ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE. Prior Corrective Action dates remain applicable. 8 of 8 - Corrective Actions from prior FIR NOT addressed. 1.) Weed encroachment at crude oil tanks, produced H2O tank, & heater treater sites. Remove, manage, & control weeds at crude oil tanks, produced H2O tank, & heater treater sites. Comply with Rule 603.f. Original Corrective Action date: 11/03/2017. See photos. 2.) Unused Equipment (Pipe) at S. side of pit. Refer to Rule 603.f for guidance. Remove unused equipment at S. side of pit. Comply w/ Rule 603.f. Original Corrective Action date: 11/17/2016. See photos. 3.) Spill & Stained soil at wellsite. <= 1 Bbl. Stained soil at pumping unit engine house. Stained soil at crude oil tanks loadout. Remove or remediate stained soil & oily waste. Material around wellhead has been worked but impacted soil remains in place. Visual and odor evidence of hydrocarbon impacts to soil remain present. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Comply w/ Rule 605.d. Oily soil must be handled in accordance with Rule 907.e. but cannot be added to existing land treatment area. Original Corrective Action date: 09/19/2016. See photos 4.) Flowlines from treater to former pit NOT properly abandoned. Refer to Rule 1103 for guidance. Properly abandon flowlines to former pit. Comply w/ Rule 1103. Original Corrective Action date: 03/20/2017. See photos. 5.) Crude oil tanks berm integrity compromised. Erosion & burrows in and on berms. Maintain berms to comply w/ Rule 906.d(1). Original Corrective Action date: 04/09/2017. See photos 6.) Rust on crude oil tank. Repair & paint tanks to comply w/ Rule 804 & 605.d (Visual & Mechanical conditions). Original Corrective Action date: 04/24/2018. See photos. 7.) Maintain berms listed as CA twice. 8.) Weed encroachment at wellsite & pit excavation area. Remove, manage, & control weeds at wellsite & pit excavation area. Comply with Rule 603.f. Corrective Action date: 05/10/2019. See photos.</p> <p>Last produced Apr 2015. MIT is now current as of 06/26/2019 per Approved Form 21 173418</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petrie	10/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402519433	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5278223
696302593	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5278221