

Inspection Photos  
Operator: Elm Ridge  
API: 067-06381  
Date: 10/15/2020



Photo 1. View of the project area from the northeastern corner facing center. Project area is recontoured. However, vehicles have been accessing the site and crushing vegetation. Access does not appear to have specific need as turnaround is on well pad.





Photo 2. View of the western project area from the southwestern corner facing northward. Roads need to be closed and reclaimed.






Photo 3. View of the beginning of Transect 1, within the project area facing northeastward. Inset shows a birds-eye view of vegetation at this midpoint of Transect 1, with dense kochia.





Photo 4. View of the project area from the mid-point along Transect 1, facing northward. Dense kochia observed.





Inset



Transect 2  
10/15/2020  
067-06381  
Within the Reference Area

10.15.2020

Photo 5. View of the beginning of Transect 2, within the reference area facing northward. Inset shows a birds-eye view of vegetation at the midpoint of Transect 2, with smooth brome.





Photo 6. View of musk thistles within the southeastern project area. Approximately 200 individuals observed.





Photo 7. View of Russian knapweeds within the southern project area. Approximately 1000 individuals observed.





Photo 8. View of area within the northeastern project area with bare soils and little revegetation.





Photo 9. View of area within the southeastern project area where revegetation is progressing, largely with smooth brome.