

Inspection Photos

API: 071-09664

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 11/3/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09664 | Date: 11/3/2020

Inspection Photos



Photo 1. Facing east toward the access road which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09664 | Date: 11/3/2020

Inspection Photos



Photo 2. Facing east along the access road. There is erosion occurring down the road which is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09664 | Date: 11/3/2020

Inspection Photos



Photo 3. Facing northeast toward the location cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09664 | Date: 11/3/2020

Inspection Photos



Photo 4. Facing southeast toward the location which has not been recontoured and reclaimed..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09664 | Date: 11/3/2020

Inspection Photos



Photo 5. Facing northeast toward the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09664 | Date: 11/3/2020

Inspection Photos



Photo 6. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09664 | Date: 11/3/2020