

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/29/2020

Submitted Date:

11/04/2020

Document Number:

688800811**FIELD INSPECTION FORM**Loc ID 333401 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215007	WELL	PR	01/12/1983	GW	067-06612	HANSTEDT 07U-01 1	EI
284910	WELL	PR	05/31/2006	GW	067-09171	HANSTEDT 07U-01 3	EI

General Comment:

On October 29, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Hanstedt 7U-1 #1. For the most recent field inspection report of this facility, please refer to document #685304890.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Free standing sign near PBV has contents, capacity, and NFPA placard listed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign. Operator is labeled as Simcoe LLC on location signs.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted on location signs.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Stock panel fencing around telemetry equipment, meter run, separators, and PBV.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Pump jacks have stock panel enclosures and guard fencing.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chain link perimeter fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electrical supply equipment.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Electric motors.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	PBV STEEL		37.201460,-107.763833	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>215007</u>	Type:	<u>WELL</u>	API Number:	<u>067-06612</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>284910</u>	Type:	<u>WELL</u>	API Number:	<u>067-09171</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On October 29, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Hanstedt 7U-1 #1. For the most recent field inspection report of this facility, please refer to document #685304890.	hughesjo	11/04/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800812	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5284221