

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06611**  
**Date: 11/2/2020**



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with crested wheatgrass and smooth brome. Musk thistles appear to be herbicide-treated.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of reference area comprised of mosaic of sagebrush shrubland with squirreltail and western wheatgrass, along with irrigated grass fields.



Photos 5/6. View of closed gates after entering (left) and leaving (right) project area.