

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2020

Submitted Date:

11/04/2020

Document Number:

699302889**FIELD INSPECTION FORM**

Loc ID 336530 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296367	WELL	SI	04/01/2019	OW	123-26724	HAUCK 17-29	SI
296979	WELL	SI	04/01/2019	OW	123-26723	HAUCK 24-29	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	chainlink topped with barb wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	hog fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 5		
Comment:	automation and electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:	exposed at surface		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 296367 Type: WELL API Number: 123-26724 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI since 4-1-2019, Form 17 Doc # 402513140 submitted on 10-16-2020 and is approved.

Corrective Action: _____ Date: _____

Facility ID: 296979 Type: WELL API Number: 123-26723 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI since 4-1-2019, Form 17 Doc # 402513136 submitted on 10-16-2020 and is approved.

Corrective Action: _____ Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Wednesday 11/4/2020 at approximately 1050 hrs. I, Inspector Robbie Revas,
 Conducted an on-site inspection at a Kerr McGee location:

Hauck 17-29 at API #05-123-26724

in Weld County Colorado.
 While there, I observed a wellsite. Hauck 24-29 SI since 4-1-2019, Form 17 Doc #
 402513136 submitted on 10-16-2020 and is approved. Hauck 17-29 SI since 4-1-2019
 Form 17 Doc # 402513140 submitted on 10-16-2020 and is approved.
 During this inspection no compliance issues were observed:
 See attached photos.
 Location is dry, weather is clear.
 No follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

revasr

11/04/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302890	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5284476