

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/05/2020

Submitted Date:

11/05/2020

Document Number:

696302630

**FIELD INSPECTION FORM**
 Loc ID 318940 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 49407

Name of Operator: KUGLER\* DEAN &amp; JOE DBA D-J OIL COMPANY

Address: P O BOX 72

City: NEW RAYMER State: CO Zip: 80742

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Binschus, Chris		chris.binschus@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	
,		dnr_cogccengineering@state.co.us	
Kugler, Dean		dlkug@yahoo.com	
,		dakugler@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242543	WELL	SI	12/01/2015	OW	123-10334	MYERS F-1	SI

**General Comment:**

This is a Follow-Up Inspection to FIR 696301675 dated 04.13.2020 and 696300626 dated 09.25.2019. Any Corrective Actions not yet addressed are still applicable with original Corrective Action Date.

## Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused Production Equipment STILL remains; Same Corrective Action Date is still active - Unused Heater Treater, 4 Deadman Anchors, Pumping Unit, Engine, Produced Water and Crude Oil Tanks.		
Corrective Action:	Comply with Rule 603.f.	Date:	11/25/2019
Type	WEEDS		
Comment:	Weeds are actively growing on the entire location, see photos		
Corrective Action:	Comply with Rule 603.f.	Date:	11/20/2020

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:		Shares berm with the Crude Oil Tank			
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.638020,-103.855310	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 242543 Type: WELL API Number: 123-10334 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well appears to have been Plugged and Abandoned around 07.08.2019. Well Bore at surface, now has a Metal Cap. Not yet Cut and Capped.  
Approved Form 6 2304070 dated 04.15.2019  
No Form 6 Subsequential has been submitted to date.

Corrective Action: Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, will be filed with the Director. Per Rule 311.b. (1)

Date: 12/04/2020

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 10/06/2020 at approximately 15:24, I, Inspector Erica Petrie, conducted a Field Inspection at Kugler* Dean and Joe DBD D-J Oil Company, Myers F-1 at Location #318940 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>The Well Bore is still at Surface, not yet Cut and Capped. Has been covered is a Metal plate.</p> <p>Weeds are actively growing on the entire location, see photos. Comply with Rule 603.f. Corrective Action Date 11/20/2020.</p> <p>Multiple Unused Equipment: Separator, Pumping Unit, Horse's Head, Wellhead parts and fittings, Engine, Engine Shed, Crude Oil Tanks (2), Produced Water Tanks. Comply with Rule 603.f. Corrective Action Date 11/25/2019. Final Reclamation to begin 90 days after Plugging and Abandonment.</p> <p>Well appears to have been Plugged and Abandoned around 07.08.2019, no Form 42 Notice of Plugging Operations was Submitted. Approved Form 6 #2304070 dated 04.15.2019. No Form 6 Subsequential has been Submitted to date. Wellbore is covered with Metal Plate at Surface, not yet Cut and Capped. Submit Subsequent Report of Abandonment, Form, 6. Within 30 days after abandonment, the Well Abandonment Report, Form 6 - Subsequent Report of Abandonment, shall be filed with the Director. Per Rule 311.b.(1). Corrective Action Date 12.04.2020 or to be determined by COGCC Engineering Staff.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection report.</p>	petrie	11/05/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696302631	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5285524">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5285524</a>