

Inspection Photos
Operator: Hilcorp Energy
API: 067-06442
Date: 11/5/2020



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Berms are installed at the edge of the well pad where erosion was identified during previous reclamation inspection. Weeds appear to be controlled at this time.



Photo 3. View of reference area facing southward. Vegetation is comprised of a mosaic of gambel oak shrubland, with ponderosa pine, pinyon and juniper trees, shrubs such as mountain mahogany, yucca, and grasses/forbs such as rocky mountain penstemon, squirreltail, western wheatgrass, smooth brome, and badlands.