

Inspection Photos

API: 073-06776

Operator: KODA EXPLORATION LLC

Inspection Date: 11/5/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 1. The drilling sign is posted at the beginning of the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 2. Facing southwest along the road used to access the site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 3. Facing west toward the location..



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 4. The topsoil pile has been tracked but is not sufficient to stabilize and maintain the topsoil pile. The topsoil is susceptible to erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 5. Facing southwest on top of the topsoil berm.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 6. Soil roughening has occurred around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 7. Facing northeast at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020

Inspection Photos



Photo 8. Facing northeast at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06776 | Date: 11/5/2020