

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2020

Submitted Date:

11/09/2020

Document Number:

700404100

FIELD INSPECTION FORM

Loc ID 311820 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
 Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
 Address: 5057 KELLER SPRINGS RD STE 650
 City: ADDISON State: TX Zip: 75001

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Energy, Foundation		regulatory@foundationenergy.com	Regulatory

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231046	WELL	PR	07/01/2020	GW	103-08715	COLUMBINE SP FED 13-24-4-104	PR

General Comment:

A routine inspection identified the following compliance issues:
 1) Insufficient stormwater BMP to prevent sediment from flowing over the location. Photos 1, 4, 5. Complete by 12-9-2020.
 This is a summary of inspection report 700404100.

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#		corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Ancillary equipment	# 1		
Comment:	Communication tower.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS

CONDENSATE	1	300 BBLs	STEEL AST			
------------	---	----------	-----------	--	--	--

Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate			Adequate		
Comment:						
Corrective Action:					Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		

Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate			Adequate		
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No						
Comment:						
Corrective Action:					Date:	

Flaring:

Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 231046 Type: WELL API Number: 103-08715 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

Comment: [Insufficient stormwater BMP to prevent sediment from flowing over the location.](#)
[Stormwater sediment is flowing off the hillside on the east side of the location. Then over the location and off the west side of the location. Vegetation on the ranch is chocking out just west of the location from sediment. The space between the berm & hillside is filled with sediment.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 12/09/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700404101	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5286963