

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/02/2020

Submitted Date:

11/02/2020

Document Number:

699802034

**FIELD INSPECTION FORM**

Loc ID: 312662      Inspector Name: De Paolo, Corey      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**  
 THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**  
 9 Number of Comments  
 5 Number of Corrective Actions  
 Corrective Action Response Requested

**Operator Information:**  
 OGCC Operator Number: 53255  
 Name of Operator: MARALEX RESOURCES INC  
 Address: P O BOX 338  
 City: IGNACIO      State: CO      Zip: 81137

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, BLM		jbyers@blm.gov	
Graves, Jim		mrinc20@maralexinc.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Jordan, Reid		maralextechjr@gmail.com	
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222107	WELL	SI	11/01/2014	GW	077-08709	SULFUR GULCH 9-98-2 1	SI

**General Comment:**

**COGCC Inspection Report Summary**  
 On Monday 11/2/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW, Location #312662 in Mesa County Colorado.  
 Refer to document #699801094 inspection conducted on 5/13/20. Not all corrective actions have been completed.  
 During this inspection the following possible compliance issues were observed: Tank label and placards are weathered and not legible. See photo #1175 and #2157 with a previous corrective action date of 3/2/20. Tank by wellhead is not properly labeled. See photo #1179 and #2156 with a previous corrective action date of 3/2/20. Multiple places with weeds and debris on location. See photo #2158 with a corrective action date of 2/2/20. Vegetation growing on tank containment berm. See photo #2159. With a corrective action date of 12/12/20. Well last produced October 2014. Last MIT performed on 11/13/2013. MIT required with a previous corrective action date of 1/31/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

<b>Location</b>			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Tank label and placards are weathered and not legible. See photo #1175 and #2157		
Corrective Action:	Operators shall maintain signs in a legible condition, and shall replace damaged signs. Replace tank label and placards.	Date:	03/03/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Tank by wellhead is not properly labeled. See photo #1179 and #2156		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material are required to be marked and placarded. Properly label tank.	Date:	03/03/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	_____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Multiple places with debris on location. See photo #2158		
Corrective Action:	Production facilities, shall be kept free of weeds and debris. Remove all debris from location.	Date:	02/02/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date

Comment:	Unmarked tank by wellhead		Date:	
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Plunger Lift	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:			Date:	
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	Vegetation growing on tank containment berm. See photo #2159			Date:
Corrective Action:	Secondary containment structures shall be sufficiently impervious to contain discharged material. Remove vegetation and repair berm.			Date: 12/12/2020

**Venting:**

Yes/No	NO	Date:
Comment:		
Corrective Action:		

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 222107 Type: WELL API Number: 077-08709 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well last produced October 2014. Last MIT performed on 11/13/2013 refer to document #2450053. MIT required.

Corrective Action: Well is overdue for Mechanical Integrity Test. Perfrom MIT on well. Date: 01/31/2020

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						
Ditches						
		Berms				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402523999	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282917</a>
699802035	Photos for Insp. #699802034	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282909">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5282909</a>