

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402525348

Date Received:

11/04/2020

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10539

Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP

Address: 1125 ESCALANTE DR

City: RANGELY State: CO Zip: 81648

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Ronnie Plummer</u>	<u>970-629-3520</u>	<u>rplummer@utahgascorp.com</u>
<u>Steven Hale</u>	<u>970-290-2912</u>	<u>shale@utahgascorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 699700218

Inspection Date: 10/13/2020

FIR Submit Date: 10/29/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: UTAH GAS OP LTD DBA UTAH GAS CORP

Company Number: 10539

Address: 1125 ESCALANTE DR

City: RANGELY State: CO Zip: 81648

LOCATION - Location ID: 315594

Location Name: MFS FEDERAL-62S103W Number: 7SENW County: \_\_\_\_\_

Qtrqtr: SENW Sec: 7 Twp: 2S Range: 103W Meridian: 6

Latitude: 39.891077 Longitude: -109.000747

FACILITY - API Number: 05-103-00 Facility ID: 315594

Facility Name: MFS FEDERAL-62S103W Number: 7SENW

Qtrqtr: SENW Sec: 7 Twp: 2S Range: 103W Meridian: 6

Latitude: 39.891077 Longitude: -109.000747

CORRECTIVE ACTIONS:

1 ☒ CA# 144066

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/02/2020

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator Comment: Well sign was on the well head. This site has been inspected several times in the last 12 months by COGCC area inspector, Rick Moran.

COGCC Decision: Approved via an AMI

COGCC Representative: It is apparent that the tank battery sign was temporarily removed for the installation of MWs.

COGCC Supervisor: Review of previous inspections the tank battery sign had accurate information, in place, and compliant to Rule 210.b. It is apparent that the tank battery sign was temporarily removed for the installation of MWs.

2 ☒ CA# 144067

Corrective Action: Comply with Rule 603.f .

Date: 11/17/2020

Response: CA COMPLETED

Date of Completion: 10/16/2020

Operator Comment: Metal stair-case that was identified as "unused equipment" was moved temporarily for the Environmental sampling to be done inside the earthen berm. Once drilling and sampling was completed 10-13-20, stair case was replaced.

COGCC Decision: Approved pending re-inspection

COGCC Representative: The COGCC appreciates the Operator's explanation in the comments below.

COGCC Supervisor: At the time of inspection, the Environmental EPS Staff observed a metal stair-case lying on the berm adjacent to a monitoring well. The COGCC appreciates the Operator's explanation in the comments below.

#### OPERATOR COMMENT AND SUBMITTAL

Comment: We are submitting this FIRR on basis that (2) of these corrective actions were inaccurate and should not have been called out by Environmental COGCC staff.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Steven Hale

Signed: \_\_\_\_\_

Title: Environmental Specialist

Date: 11/4/2020 11:44:40 AM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402525348	FIR RESOLUTION SUBMITTED
402525376	Photo evidence of well sign

Total Attach: 2 Files