

# Inspection Photos

API: 071-07680

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 11/10/2020



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 11/10/2020

## Inspection Photos



**Photo 1.** Facing northwest toward the access road. There is erosion along the access road at Lar/Long: 37.15772,-104.88855. This area need to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 11/10/2020

## Inspection Photos



**Photo 2.** Facing northeast along the access road. There is erosion along the access road at Lar/Long: 37.15877,-104.88882. This area need to be repaired and stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 11/10/2020

## Inspection Photos



**Photo 3.** The culvert along the access road is filled in with sediment. Approx. Lat/Long:37.15953,-104.88851.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 11/10/2020

## Inspection Photos



**Photo 4.** Facing northeast toward the access road. Stormwater is not flowing toward the culvert and is going across the road creating erosion shown in next photo. Previous corrective action has not been performed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 11/10/2020

## Inspection Photos



**Photo 5.** There is erosion occurring off the fill slope from stormwater flowing across the road shown in previous photo.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 11/10/2020

## Inspection Photos



**Photo 6.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-07680 | Date: 11/10/2020