

Inspection Photos

API: 071-07778

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 11/10/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

Inspection Photos



Photo 1. Facing northwest along the main access road. The culvert along the access road is filled in with sediment. Approx. Lat/Long:37.15036,-104.88730.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

Inspection Photos



Photo 2. Facing north along the main access road. The culvert along the road is damaged. Lat/Long:37.15100,-104.88755.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

Inspection Photos



Photo 3. Facing southwest along the access road ascending the hillside. The road has been regraded. Additional BMP's are needed along the road side to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

Inspection Photos



Photo 4. Facing south along the access road ascending the hillside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

Inspection Photos



Photo 5. The culvert along the access road is filled in with sediment. Approx. Lat/Long:37.15042,-104.88852.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020

Inspection Photos



Photo 6. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07778 | Date: 9/11/2020