

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: [Brown AG Fencing](#)

Corrective Action:

Date: _____

Equipment:

Type: Horizontal Heated Separator

1

corrective date

Comment:

Corrective Action:

Date: _____

Type: Bird Protectors

2

Comment:

Corrective Action:

Date: _____

Type: Bradenhead

1

Comment:

Corrective Action:

Date: _____

Type: Emission Control Device

1

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift

#

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment

1

Comment: [automation](#)

Corrective Action:

Date: _____

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	BV CONCRETE		,
Comment: 60 BBL					
Corrective Action: <input type="text"/>		Date: _____			

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: shares containment with oil tanks				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					Date:
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: shares containment with oil tanks				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					Date:
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Venting:	
Yes/No	NO

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 201315 Type: WELL API Number: 001-06718 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 11/10/20 at approximately 1200 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- Box Elder H 2 Company Name- Extraction oil and gas API- 05-001-06718 In Adams County Colorado. While there, I observed shut in well. During this inspection the following possible compliance issues were observed: Stained soil near flowline by wellhead see pic 2,3 Comply with 603 f. 12/10/20 Mechanical issue on flowline near wellhead see pic 2,3 Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.12/10/20</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. At time of inspection weather conditions were sunny, cold, recent snow.</p> <p>This is a summary of inspection report.</p>	medinaj	11/10/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501899	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5288636