

TEP
RMV 237-28
Location # 335130



location



location

TEP
RMV 237-28
Location # 335130



location



Rutting



TEP
RMV 237-28
Location # 335130



Rutting



Rutting/ Lack of tracking controls

TEP
RMV 237-28
Location # 335130



Previous inspection photo of piping



follow up photo



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
RMV 237-28
Location # 335130



Previous inspection photo of piping



follow up photo