

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2020

Submitted Date:

11/03/2020

Document Number:

699802044

**FIELD INSPECTION FORM**

Loc ID: 432260    Inspector Name: De Paolo, Corey    On-Site Inspection:     2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1401  
City: DENVER    State: CO    Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 12 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432258	WELL	PR	06/27/2014	GW	045-21934	Homer Deep Unit 9-41BH	PR
432261	WELL	PR	03/01/2018	GW	045-21935	Homer Deep Unit 9-41AH	PR
438407	WELL	PR	03/03/2015	GW	045-22488	Homer Deep Unit 9-41CH	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Tuesday 11/3/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Homer Deep Unit /9-41, Location #432260 in Garfield County Colorado. While there, I observed normal production operations. During this inspection the following possible compliance issues were observed: Culvert inlet and outlet blocked by sediment accumulation. See photo #2175 and #2176. Culvert located at entrance to location by separators and meter runs. Rill erosion occurring on West end of location near wellheads. See photo #2174. Cattle guard in access road filled with sediment due to tracking. See photo #2177 with a corrective action date of 11/18/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:			Date:
<b>Equipment:</b>			
Type:	Plunger Lift	# 3	corrective date
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank by wellheads		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 432258 Type: WELL API Number: 045-21934 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 432261 Type: WELL API Number: 045-21935 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 438407 Type: WELL API Number: 045-22488 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Rip Rap						
		Culverts				
		Berms				
Sediment Traps						
		Other	Fail			Cattle guard filled with sediment
		Ditches				
Ditches	Fail					Rill erosion occurring on west end of location
		Gravel				
Gravel						
Culverts	Fail					Culvert inlet and outlet blocked by sediment

Comment: [Culvert inlet and outlet blocked by sediment accumulation. See photo #2175 and #2176. Culvert located at entrance to location by separators and meter runs. Rill erosion occurring on West end of location near wellheads. See photo #2174. Cattle guard in access road filled with sediment due to tracking. See photo #2177.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 11/18/2020

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402525063	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5283852">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5283852</a>
699802045	Photos for Insp. #699802044	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5283846">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5283846</a>