

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2020

Submitted Date:

11/05/2020

Document Number:

688800813

FIELD INSPECTION FORM

Loc ID 334193 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 16 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre		sabre.beebe@bpx.com	All Inspections
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258541	WELL	PR	08/11/2007	GW	067-08363	HANSTEDT 07U-01 2	EI
284911	WELL	PR	02/01/2020	GW	067-09172	HANSTEDT 07U-01 4	EI

General Comment:

On October 29, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Hanstedt 7U-1 #4. For the most recent field inspection report of this facility, please refer to document #685302184.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance. Simcoe LLC listed as operator.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Free standing sign near PBV. Simcoe LLC listed as operator. Sign is labeled with contents, capacity, and has NFPA placard.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Concrete pad for pump jack near the #4 well head is not in use.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/04/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Stock panel enclosure around all production equipment on site.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Steel pipe barricade fencing around pipeline risers.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Guard fencing present.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Stock panel enclosures.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Pipeline risers and valves.		
Corrective Action:			Date:
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 2		
Comment:	Electric motors.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.207627,-107.763589	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	

Other (Type) _____	
--------------------	--

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No					
Comment:					
Corrective Action:					Date:

Flaring:

Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 258541 Type: WELL API Number: 067-08363 Status: PR Insp. Status: EI

Facility ID: 284911 Type: WELL API Number: 067-09172 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On October 29, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Hanstedt 7U-1 #4. For the most recent field inspection report of this facility, please refer to document #685302184. A concrete pad for a pump jack is not in use near the #4 well head.	hughesjo	11/05/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402526688	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5285413
688800814	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5285408