

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 458678 Type: WELL API Number: 123-48437 Status: DG Insp. Status: DG**Well Drilling**Rig: Rig Name: Ensign 162 Pusher/Rig Manager: Josh
Permit Posted: SATISFACTORY Access Sign: SATISFACTORY**Well Control Equipment:**Pipe Ram: YES Blind Ram: YES Hydril Type: YES
Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES**Drill Fluids****Management:**Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: YES Disposal Location: Waste ManagementComment: Drilling ahead, 9059' TD at the time of inspection.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 11/12/20 at approximately 0907, I, Inspector Adam Burns, conducted an on-site inspection at Silverton 4 North Pad, Operated by Confluence DJ LLC, at location ID: 458676 in Weld County Colorado. While there, I observed drilling operations by Ensign 162 drilling at 9059' TD, drilling ahead, on the Silverton 5-2-2L API #05-123-48437. No violation of the COGCC rules were observed at the time of inspection. Continuing education inspections</p>	burnsa	11/12/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699102723	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5289750