

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/12/2020

Submitted Date:

11/12/2020

Document Number:

700404190**FIELD INSPECTION FORM**

Loc ID 311834 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|-----------------------------|---------------------------------|
| , Utah Gas Corp | 720-425-0303 | inspections@utahgascorp.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 232187 | WELL | PR | 03/01/2018 | GW | 103-09858 | LOWER HORSE DRAW 2231 | PR |

General Comment:

[A follow up inspection of FIR document 700403837.](#)

[The following compliance issues were resolved:](#)

- [1\) Well head sign was attached to well.](#)

[This is a summary of inspection report 700404190.](#)

LocationOverall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|-----|-------------|
| Comment: | 911 | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|--------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------------|-----------|-------|-----------------|
| Type: Deadman # & Marked | # 4 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Other | # 1 | | |
| Comment: | Building. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|----------------|---|----------|----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | <50 BBLS | Open Top | | , |
| Comment: | | | | | |

| | | | |
|-------------------------|----------|---------------------|-------------|
| Corrective Action: | | Date: | |
| Paint | | | |
| Condition | Adequate | | |
| Other (Content) | | | |
| Other (Capacity) 50 bbl | | | |
| Other (Type) | | | |
| Berms | | | |
| Type | Capacity | Permeability (Wall) | Maintenance |
| Earth | Adequate | | Adequate |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 232187 | Type: WELL | API Number: 103-09858 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | PR | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 700404191 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5290508 |