

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/12/2020

Submitted Date:

11/13/2020

Document Number:

699602039

FIELD INSPECTION FORM

Loc ID 303875 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 38 PALMER CREST CT
City: SPRING State: TX Zip: 77381

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253736	WELL	PR	03/22/1995	GW	125-07614	FRANSON 7-33	PR

General Comment:

[Routine FIR](#)

Location			
Lease Road:			
Type	Access		
comment:	Cropland with seasonal access		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:
Type	BATTERY		
Comment:	MR		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	NA		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:			Date:
Equipment:			
Type:	Gas Meter Run	# 1	corrective date
Comment:	Calibration cert in place		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:	NA		
Corrective Action:			Date:
Flaring:			
Type			
Comment:	NA		
Corrective Action:			Date:

Inspected Facilities

Facility ID: 253736 Type: WELL API Number: 125-07614 Status: PR Insp. Status: PR

Producing Well

Comment: [GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Cropland with rotational tillage](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602040	GMR-Calibration cert.- Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5291040