

Inspection Photos
Operator: BP America
API: 067-08645
Date: 11/13/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing southward. Revegetation is in a grazed condition, and appears progressing with fourwing saltbush, crested wheatgrass, and western wheatgrass. Monitoring and potential livestock exclusion are needed to ensure grazed vegetation recovers.



Photo 3. View of reference area mosaic of irrigated and non-irrigated grass and shrub fields with black sage, Indian ricegrass, western wheatgrass, and James galleta.



Photos 4/5. View of closed gates after entering (left) and leaving (right) location.