

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2020

Submitted Date:

11/16/2020

Document Number:

699802102**FIELD INSPECTION FORM**
 Loc ID 334489 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**24 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282733	WELL	PR	08/01/2020	GW	077-09003	VEGA UNIT 34-124	PR
282734	WELL	SI	07/01/2020	GW	077-09002	VEGA UNIT 34-12	TA
282735	WELL	PR	01/20/2006	GW	077-09001	VEGA UNIT 33-42	PR
282736	WELL	PR	03/12/2007	GW	077-09000	VEGA UNIT 33-43	PR
285018	WELL	PR	03/09/2007	GW	077-09084	VEGA UNIT 33-431	PR
285461	WELL	PR	12/12/2012	GW	077-09091	VEGA UNIT 33-441	PR
285462	WELL	SI	08/01/2020	GW	077-09090	VEGA UNIT 33-421	SI

**General Comment:****COGCC Inspection Report Summary**

On Monday 11/16/20 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC Vega /13 Pad, Location #334489 in Mesa County Colorado.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Flowline riser not LO/TO. See photo #2243 with a corrective action date of 12/16/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Flowline riser not LO/TO. See photo #2243		
Corrective Action:	Flow line risers not LO/TO or marked are considered unused equipment. Properly LO/TO or plug and mark flowline riser.	Date:	12/16/2020

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence around location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		

Corrective Action:		Date:	
<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tank by wellheads		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig heater		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	spill response trailer		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Trash bin		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well TA		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Pump in pump house		
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Injection well		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallon
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Separate containment</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Separate containment</a>				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	1000 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Concrete	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Separate containment				
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities				
Facility ID: 282733	Type: WELL	API Number: 077-09003	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 282734	Type: WELL	API Number: 077-09002	Status: SI	Insp. Status: TA
<b>Idle Well</b>				
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned      Reminder: _____				
Comment: Well last produced June 2019. Note well was found to be temporarily abandoned with no MIT or form 4 requesting TA status on record.				
Corrective Action:			Date:	
Facility ID: 282735	Type: WELL	API Number: 077-09001	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 282736	Type: WELL	API Number: 077-09000	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 285018	Type: WELL	API Number: 077-09084	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 285461	Type: WELL	API Number: 077-09091	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 285462	Type: WELL	API Number: 077-09090	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____				
Comment: Last produced July 2020				
Corrective Action:			Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms						
Sediment Traps						
Gravel						
		Gravel				
Ditches						
		Ditches				
		Berms				
		Sediment Traps				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802103	Photos for Insp. #699802102	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292531">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292531</a>