

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/09/2020

Submitted Date:

11/12/2020

Document Number:

701001679**FIELD INSPECTION FORM**
 Loc ID 303960 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

| Contact Name | Phone          | Email                       | Comment |
|--------------|----------------|-----------------------------|---------|
| Jones, Greg  | (970) 630-3909 | greg.jones@ownresources.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253845      | WELL | PR     | 01/05/1996  | GW         | 125-07723 | BAGLEY 3-12   | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |                           |       |  |
|--------------------|---------------------------|-------|--|
| <b>Lease Road:</b> |                           |       |  |
| Type               | Access                    |       |  |
| comment:           | Two track through pasture |       |  |
| Corrective Action  | L                         | Date: |  |

Overall Good: ☒

|                      |                    |       |  |
|----------------------|--------------------|-------|--|
| <b>Signs/Marker:</b> |                    |       |  |
| Type                 | OTHER              |       |  |
| Comment:             | Lease signs by VGS |       |  |
| Corrective Action:   |                    | Date: |  |
| Type                 | WELLHEAD           |       |  |
| Comment:             | Lease sign by unit |       |  |
| Corrective Action:   |                    | Date: |  |

|                           |  |             |
|---------------------------|--|-------------|
| Emergency Contact Number: |  |             |
| Comment:                  |  |             |
| Corrective Action:        |  | Date: _____ |

|                           |                                     |       |
|---------------------------|-------------------------------------|-------|
| <b>Good Housekeeping:</b> |                                     |       |
| Type                      | STORAGE OF SUPL                     |       |
| Comment:                  | Horsehead removed and stored neatly |       |
| Corrective Action:        |                                     | Date: |

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |   |       |
|--------------------|---|-------|
| <b>Fencing/:</b>   |   |       |
| Type               | LOCATION  |       |
| Comment:           | Wire fence around entire location                       |       |
| Corrective Action: |   | Date: |
| Type               | PUMP JACK   |       |
| Comment:           | Metal panels around unit, wellhead, VGS and meter sheds |       |
| Corrective Action: |   | Date: |

|                    |  |       |
|--------------------|--|-------|
| <b>Venting:</b>    |  |       |
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

|                 |  |
|-----------------|--|
| <b>Flaring:</b> |  |
| Type            |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |  |       |      |             |           |         |    |               |    |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 253845   | Type: | WELL | API Number: | 125-07723 | Status: | PR | Insp. Status: | PR |
| Producing Well       |  |       |      |             |           |         |    |               |    |
| Comment:             | Producing. Casing production. Downhole equipment still in wellbore. Central meter run for (Bagely 3-12, 4-12, 5-12 & 8-12) |       |      |             |           |         |    |               |    |
| Corrective Action:   |  |       |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 701001714    | location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292730">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5292730</a> |