

**TEP ROCKY MOUNTAIN LLC**  
**Federal SG 43-28**  
**Location ID: 334978**



**Staining around SG 42-28 and SG 342-28  
has been cleaned up.**

**TEP ROCKY MOUNTAIN LLC**  
**Federal SG 43-28**  
**Location ID: 334978**



**Soft compacted pad is wet and rutting.**

# TEP ROCKY MOUNTAIN LLC

## Federal SG 43-28

### Location ID: 334978



**Riling of soft cut slope around tank battery.**

**TEP ROCKY MOUNTAIN LLC**  
**Federal SG 43-28**  
**Location ID: 334978**



**Rill of soft cut slope around tank battery.**

**TEP ROCKY MOUNTAIN LLC**  
**Federal SG 43-28**  
**Location ID: 334978**



**Movement of storm water is washing away base under tank battery berm.**

**TEP ROCKY MOUNTAIN LLC**  
**Federal SG 43-28**  
**Location ID: 334978**



**Movement of storm water is washing away  
base under tank battery berm.**

**TEP ROCKY MOUNTAIN LLC**  
**Federal SG 43-28**  
**Location ID: 334978**



**Soft compacted check dam is riling.**

**TEP ROCKY MOUNTAIN LLC**  
**Federal SG 43-28**  
**Location ID: 334978**



**Wheel ruts starting from check dam at tank battery.**