

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2020

Submitted Date:

11/18/2020

Document Number:

699302980**FIELD INSPECTION FORM**Loc ID 333156 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gintautas, Peter		peter.gintautas@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240989	WELL	PR	04/01/2019	OW	123-08777	JILLSON 'A' 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate will need to be addressed in the near future		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:	Date: _____		

Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical Issue, possible casing or bradenhead leak below surface.		
Corrective Action:	comply with Rule 605.d	Date:	12/03/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		
Other	WELLHEAD			
Comment:	Salt water is surfacing around casing, running down the access road and pooling			
Corrective Action:	comply with Rule 906.b			Date: 11/19/2020

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	barb wire fencing in disrepair and needs attention or to be removed		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 240989 Type: WELL API Number: 123-08777 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Bradenhead tes is over 1 year old and needs to be done annually12/18/2020Corrective Action: Comply with Rule 206

Date:

Environmental**Spills/Releases:**

Type of Spill: OTHER E&P WASTE

Estimated Spill Volume: _____

Comment: Salt water surfacing from around WH casing and pooling about 6' from WH.

Corrective Action: Comply with Rule 906.b

Date: 11/19/2020

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 11/18/2020 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location:</p> <p style="text-align: right;">Jillson A 1 at API #05-123-08777 in</p> <p>Weld County Colorado.</p> <p>While there, I observed a wellsite. PR at the time of inspection. This inspection is on this well only to address compliance issue.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>906.b Spills: Salt water is surfacing around casing, running down the access road and pooling. CA date 11-19-2020</p> <p>605.d Mechanical Issue: Possible casing or bradenhead leak below surface. CA date 12-3-2020</p> <p>206 reporting: Bradenhead test is over 1 year and needs to be done annually. CA date 12/18/2020.</p> <p>See attached photos.</p> <p>Location: dry, Weather: cloudy.</p> <p>I spoke with Hannah at 1038 Hrs. Secretary with KP Kauffman told her about the Leak/Spill around the WH and casing. I gave her my cell phone number and she said she would relate it to the field operator and have them give me a call with any questions.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	11/18/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302981	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293849