

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2020

Submitted Date:

11/18/2020

Document Number:

699302987**FIELD INSPECTION FORM**Loc ID 318251 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240965	WELL	PR	10/01/2018	GW	123-08753	CHARLES ELZI ESTATE 1	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	well is located between several houses		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	WEEDS		
Comment:	dead weed inside fencing need to be addressed		
Corrective Action:	Comply with rule 603.f	Date:	12/18/2020

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	chain link topped with barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panels, meter box and transformer		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240965 Type: WELL API Number: 123-08753 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: test is over 1 year old and needs to be done annually

12/18/2020

Corrective Action: comply with rule 206

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Wednesday 11/18/2020 at approximately 1330 hrs. I, Inspector Robbie Revas,
 Conducted an on-site inspection at a KP Kauffman location:

Charles Elzi Estate at API #05-123-

08753 in Weld County Colorado.

While there, I observed a wellsite, PR at time of inspection

During this inspection the following possible compliance issues were observed:

603.f housekeeping: dead weed inside of fencing around PU. CA date 12-18-2020.

206 reporting: Braden head test is over 1 year. CA date 12-18-2020

See attached photos.

Location is dry, weather is clear.

I spoke with (Name & Title) (Company) what was discussed.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

revasr

11/18/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302988	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5293852