

Inspection Photos

Operator: BP America
API: 067-08352
Date: 11/17/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing within the project area with thickspike wheatgrass, crested wheatgrass, rubber rabbitbrush, and smooth brome.



Photos 3-5. View of musk thistles within the project area, appear to be partially treated. Surviving individuals remain. Evidence of significant infestation remains.



Photo 6. View of the southern project area from the southeastern corner facing westward.



Photo 7. View of reference area comprised of sagebrush and antelope bitterbrush shrubland with scattered pinyon and juniper trees and understory of thickspike wheatgrass, yucca, prickly pear, and narrowleaf penstemon.