

Inspection Photos
Operator: BP America
API: 067-09267
Date: 11/17/2020



Photo 1. View of the project area from the access entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with grasses, largely in a grazed condition, with crested wheatgrass and intermediate wheatgrass.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of sagebrush shrubland with scattered pinyon and juniper trees and understory of western wheatgrass, prickly pear, and blue grama.



Photos 4/5. View of closed gates (2) after leaving location.