

Inspection Photos
Operator: BP America
API: 067-08347
Date: 11/17/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with grasses such as crested wheatgrass and western wheatgrass.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of the reference area comprised of sagebrush shrubland with scattered pinyon and juniper trees and understory of grasses and forbs such as western wheatgrass and snakeweed.



Photos 5/6. View of closed gates (2) after leaving location.