

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/19/2020

Submitted Date:

11/19/2020

Document Number:

699303008**FIELD INSPECTION FORM**Loc ID 333163 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241529	WELL	PR	03/01/2019	OW	123-09318	MEREDITH 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Pump jack not being used and is disconnected from well, and no motor or power connected.		
Corrective Action:	Comply with Rule 603.f		Date: 02/19/2021

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:	Pump jack is disconnected from WH and there is no power source or motor/engine.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 241529 Type: WELL API Number: 123-09318 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: Annual Brhd Completed? #Error

Last Brhd Test Results Initial Surf Csg Pressure: Fluid Type:

End Surf Csg Pressure:

Comment: Bradenhead test is over 1 year and needs to be done annually.

12/19/2020

Corrective Action: Comply with Rule 206

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Thursday 11/19/2020 at approximately 1115 hrs. I, Inspector Robbie Revas,
 Conducted an on-site inspection at a KP Kauffman location:

Meredith 1 at API #05-123-09318 in

Weld County Colorado.

While there, I observed a wellsite. PR at the time of inspection.

During this inspection the following possible compliance issues were observed:

603.f Housekeeping: unused pump jack. CA date 2/19/2021 see photo 3

206 reporting: Bradenhead test is over 1 year and needs to be done annually. CA date 12-19-202

See attached photos.

Location: dry, Weather clear.

A follow up on this site inspection needs to be conducted to ensure the

Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

revasr

11/19/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303009	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294655