

TEP  
RMV 39-16  
Location # 335788



location



location





TEP  
RMV 39-16  
Location # 335788



Follow up inspection photo



Previous inspection photo



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
RMV 39-16  
Location # 335788



Previous inspection photo



Follow up inspection photo





**TEP**  
**RMV 39-16**  
**Location # 335788**



**Previous inspection photo**



**Follow up inspection photo**





TEP  
RMV 39-16  
Location # 335788



Previous inspection photo




Follow up inspection photo





TEP  
RMV 39-16  
Location # 335788



**Lack of stabilization**




**Lack of stabilization**





TEP  
RMV 39-16  
Location # 335788



**Lack of stabilization**



**Lack of stabilization**



TEP  
RMV 39-16  
Location # 335788



**Lack of stabilization**



**Lack of stabilization**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources