

TEP  
RWF 53-17  
Location # 335777



location



location



**TEP**  
**RWF 53-17**  
**Location # 335777**



**Previous inspection photo**



**Follow up photo still no stabilization and sediment migration, old waddle is still in place**





**TEP**  
**RWF 53-17**  
**Location # 335777**



**Previous inspection photo**



**Follow up photo**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**TEP**  
**RWF 53-17**  
**Location # 335777**



**Previous inspection photo**



**follow up photo**





TEP  
RWF 53-17  
Location # 335777



**lack of stabilization**



**lack of stabilization**





TEP  
RWF 53-17  
Location # 335777



**Access road has lack of stabilization**



**Access road has lack of stabilization**





**TEP**  
**RWF 53-17**  
**Location # 335777**



**Access road has lack of stabilization**



**Access road has lack of stabilization**




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



TEP  
RWF 53-17  
Location # 335777



**Access road has lack of stabilization**



**Access road has lack of stabilization**

