

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/17/2020

Submitted Date:

11/19/2020

Document Number:

701001727

FIELD INSPECTION FORM

Loc ID 321240 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 81480
Name of Operator: THOMAS L SPRING LLC
Address: 7400 E ORCHARD RD STE 106-S
City: GREENWOOD State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Springs, Tom	303-771-1889 off/68710	T1spring@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257026	WELL	PR	08/01/2018	GW	011-06172	WOLLERT B 3	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Other		
comment:	Gravel road to farm house		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to stairs		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tank and metal sign by tank		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:				corrective date
Type: Horizontal Heated Separator	# 1			
Comment:	HGS on north side of meter run			
Corrective Action:		Date:		
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:		Date:		

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLs	STEEL AST		38.225590,-102.765140
Comment:	Steel tank on south side of open top tank				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Berms need maintenance for capacity					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	Open Top		38.225590,-102.765140
Comment: 60bbl fiberglass open top water tank w/Adequate wildlife screening					
Corrective Action:				Date:	
Paint					
Condition					
Other (Content)					
Other (Capacity)	110bbbls				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shared berms					
Corrective Action:				Date:	
Venting:					
Yes/No					
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 257026 Type: WELL API Number: 011-06172 Status: PR Insp. Status: PR

Producing Well

Comment: Producing. Well had an audible leak from 80' away. Master valve was closed at 10:04AM. Operator was contacted at 10:40AM after well gas had subsided and pressure was dead on the flowline. Inspector left a message to return the call in regards to the well leaking and being shut it. Tom Spring returned the call at 1:55pm, with a message saying he would send a pumper to the wellhead to see whats going on

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location is farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701001758	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5294727