

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Hubert Morrison A #1 well head and pump jack.



Steel flow lines being replaced with poly pipe.

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Steel to poly transition at separator.



Poly to steel transition upstream of separator.

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Poly flow lines in open excavation.



Present termination of newly installed poly flow lines.

Inspection Photos
Location Name: Hubert Morrison A #1
API: 05-067-06899



Eventual poly to steel transition.



Photo taken from approximate location of Spill/Release Point ID #476772.