

FORM
INSPRev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2020

Submitted Date:

11/20/2020

Document Number:

688800825

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Heil, John		john.heil@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Murray, Richard		g.richard.murray@state.co.us	
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215294	WELL	SI	07/01/2020	GW	067-06899	HUBERT MORRISON A 1	EI
474315	Domestic Tap	AC			-	Domestic Tap 17SWNE	EI
476772	SPILL OR RELEASE	CL			-	Hubert Morrison A1	EI

General Comment:

On November 19, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Hubert Morrison A #1 Spill/Release Point ID #476772. For the most recent field inspection report of this facility, please refer to document #693200677. A Crossfire construction crew was on site during this inspection.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign observed near the edge of the location during this inspection. Simcoe LLC listed as the operator.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel enclosure and guard fencing.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stock panels and orange safety fencing around open excavations.		
Corrective Action:		Date:	
Equipment:			
Type: Vertical Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	Poly pipe being installed from well head to separator and from separator to off location extent of replaced steel flowline.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Domestic gas tap.		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 215294 Type: WELL API Number: 067-06899 Status: SI Insp. Status: EI

Facility ID: 474315 Type: Domestic Tap API Number: - Status: AC Insp. Status: EI

Facility ID: 476772 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
		Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On November 19, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Hubert Morrison A #1 Spill/Release Point ID #476772. For the most recent field inspection report of this facility, please refer to document #693200677. A Crossfire construction crew was on site during this inspection. During this inspection steel flow lines were being replaced with polyethylene pipe.	hughesjo	11/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800826	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5295228