

**Inspection Photos**  
**Location Name: GUNNISON ENERGY LLC FEDERAL-610S90W /32SWSE**  
**Location ID: 324459**



**Photo #2298 from entrance to location.**



**Photo #2299 Separator with small gas leak.**

## Inspection Photos

Location Name: GUNNISON ENERGY LLC FEDERAL-610S90W /32SWSE

Location ID: 324459



Photo #2300 gas leaking from a dump controller mixer inside the separator.

Photo #