

Inspection Photos

API: 071-06128

Operator: TIMBER CREEK OPERATING
OGRIS OPERATING LLC

Inspection Date: 11/19/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 11/19/2020

Inspection Photos



Photo 1. There is a plugged culvert along the main road (red arrow) causing stormwater to flow down the road. Lat/Long:37.09178,-104.93688. Corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 11/19/2020

Inspection Photos



Photo 2. The culvert is filled in with sediment causing stormwater to flow down the road. All culverts need to be maintained. Previous corrective action was not performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 11/19/2020

Inspection Photos



Photo 3. There is a long stretch of road with no BMP's to prevent erosion which was previously observed. Rock along the side could be used for check dams to slow stormwater velocity.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 11/19/2020

Inspection Photos



Photo 4. There is vehicle ruts occurring after repairs had been performed. BMP's such as gravel is needed to prevent rutting and road degradation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06128 | Date: 11/19/2020

Inspection Photos



Photo 5. Facing south toward the location.

