

Inspection Photos

API: 071-08482

Operator: TIMBER CREEK OPERATING
OGRIS OPERATING LLC

Inspection Date: 11/19/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08482 | Date: 11/19/2020

Inspection Photos



Photo 1. Storm water erosion is occurring down the side of the road. BMP's need to be installed to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08482 | Date: 11/19/2020

Inspection Photos



Photo 2. Facing southeast toward the location. Stormwater is causing erosion across and down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08482 | Date: 11/19/2020

Inspection Photos



Photo 3. Erosion shown in previous photo is caused by stormwater coming from the road past the location. Photo on the right shows that the diversion ditch is filled in causing stormwater to flow down the road. Proper diversion should be installed along with BMP's to slow stormwater velocity e.g. sediment trap, check dams.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08482 | Date: 11/19/2020