

Inspection Photos

API: 071-07204

Operator: TIMBER CREEK OPERATING
OGRIS OPERATING LLC

Inspection Date: 11/19/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 11/19/2020

Inspection Photos



Photo 1. Facing toward the location.



Inspection Photos



Photo 2. The pad which had sloughed has been recontoured and straw blanket was installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 11/19/2020

Inspection Photos



Photo 3. The straw blanket is stretched out likely due to soil movement.



Inspection Photos



Photo 4. Facing northeast. The arrow points to an outline in the embankment which appears soil has moved. This area needs to be monitored for stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 11/19/2020

Inspection Photos



Photo 5. Facing southeast toward the fill slope of the pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07204 | Date: 11/19/2020