

**FOUR CORNERS ENERGY LLC – 10754**  
**API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14**  
**Inspection Date 11/19/2020**



**Location overview from SW anchor marker looking NE (left) to SE (right)**

**FOUR CORNERS ENERGY LLC – 10754**  
**API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14**  
**Inspection Date 11/19/2020**



**Sign at SW corner of tank battery.  
Operator information updated**



**Shut in wellhead.  
Bradenhead valve plumbed to surface.**

**FOUR CORNERS ENERGY LLC – 10754**  
**API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14**  
**Inspection Date 11/19/2020**



**Tank Battery with earth berms.  
Weeds removed.**



**Tank Battery with proper tank labels.**

**FOUR CORNERS ENERGY LLC – 10754**  
**API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14**  
**Inspection Date 11/19/2020**



**Separator with earth berms.**  
**Weeds removed.**



**Meter housing and off location flowlines**

**FOUR CORNERS ENERGY LLC – 10754**  
**API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14**  
**Inspection Date 11/19/2020**



**100 bbl produced water tank ½+ full of oil/water.  
Berms repaired.**



**Oil/water level in produced water tank  
wth less than 2 feet freeboard.**

**FOUR CORNERS ENERGY LLC – 10754**  
**API# 05-033-06063 SANTA FE CANYON-FEDERAL #42-14**  
**Inspection Date 11/19/2020**



**Close up of Broken elbow on flowline.**