

Inspection Photos

11/19/2020

Operator: SG INTERESTS I LTD # 77330

Location ID: 418697

Gunnison, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 1: Photo taken from the north east corner of the Location, facing south. Photos 1-3 provide an overview of the Location from south, southwest to west.



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the cut slopes on the northeast corner of the Location. Photo shows BMPs remain missing or insufficient to stabilize and protect slopes.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 5: Photo taken from the slopes on the north end of the Location. Photo shows erosion degradation on the northern cut slope. BMPs remain missing or insufficient to stabilize and protect slopes.



Photo 6: Photo taken from the slopes on the north end of the Location, facing northwest. Photo shows erosion degradation on the northern cut slope. BMPs remain missing or insufficient to stabilize and protect slopes.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 7: Photo taken from the slopes on the north end of the Location, facing north. Photo shows erosion degradation on the northern cut slope. BMPs remain missing or insufficient to stabilize and protect slopes.



Photo 8: Photo taken from the slopes on the northeastern area of the Location, facing northwest. Photo shows erosion degradation on the northern cut slope. BMPs remain missing or insufficient to stabilize and protect slopes.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 9: Photo taken from the slopes on the northwestern area of the Location, facing north. Photo shows erosion degradation on the northern cut slope. BMPs remain missing or insufficient to stabilize and protect slopes.



Photo 10: Photo taken from the northwestern end of the Location, facing west. Photo shows ditch BMPs. Photo shows ditch has not been constructed in accordance with good engineering practices. No outlet observed to allow for sediment laden-free stormwater discharge.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 11: Photo taken from the northwestern end of the Location, facing south. Photo shows ditch BMPs. Photo shows ditch has not been constructed in accordance with good engineering practices.



Photo 12: Continued from photo 11. Photo shows outlet at ditch. BMP insufficient as an appropriate outlet to allow for sediment laden-free stormwater discharge.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 13: Photo taken from the southwest corner of the Location, facing north. Photo shows perimeter stormwater ditch. Ditch BMP has not been constructed in accordance with good engineering practices; BMP ends on the southwest end of the location and does not have a sufficient outlet to allow for sediment laden-free stormwater discharge.



Photo 14: See comments under photo 13.

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 418697



Photo 15: Photo taken from the southwest end of the Location, facing east. Photo shows fill slopes below ditch (photo 13). Photo shows BMPs remain missing or insufficient to protect slopes, and allow for sediment laden-free stormwater discharge from the ditch.



Photo 16: See comments under photo 15.